


1991 through 2005 ACURA NSX CLOCK REMOVAL INFORMATION

CAUTION: Be careful not to damage the center air vent or clock.

1. Pull the clock out with your fingers (if necessary, use a screwdriver).



Disconnect the 4P connector from the clock

Automotive Scientific Inc. Removal Instructions

* All Technical information supplied on this website is utilized at the users own risk, ASI will not be held responsible or liable in any way, shape or form for any Issues that may arise. This Information is to be utilized as a guide by Service Professionals in the Automotive Business Industry. All Technical information within our website is not to be resold or transferred in any way, this Information is for the personal use of our customer who utilized and paid for our rebuild services. This Information is for the convenience of our customers. All Information is copyrighted globally by its respected Author(s). For more information visit our website at www.Autoecu.com